Row Labels	bels Count of Area			
DTO & Styrene Truck Loading	26			
PR - 11 (Hazardous Waste Truck Rack)	26			
Fitting	11			
Other	6			
Valve	9			
Hazardous Waste	5			
T - 307 (Spent Tars Tank)	5			
Fitting	4			
Valve	1			
Train 4 Level 4	3			
PR - 04 (Main Pipe Rack North)	3			
Fitting	2			
Valve	1			
Grand Total	34			

Tag	Component	Component Type	Size	Area	Subarea	Location	Service	Stream	IA US	MA	vs	BON	TC F	L O	Γ CS	PS /	AGS	In Service
9752.00	Valve	Valve	1	Train 4 Level 4	PR - 04 (Main Pipe Rack North)	Overhead hazardous waste E	Light Liquid	Hazardous Waste	IA		1	0	0 2	2 0	0	0 (0	IN
9752.04	Flange	Fitting	1	Train 4 Level 4	PR - 04 (Main Pipe Rack North)	Overhead hazardous waste E	Light Liquid	Hazardous Waste	IA		0	0	0 1	. 0	0	0 (0	IN
9752.05	Flange	Fitting	1	Train 4 Level 4	PR - 04 (Main Pipe Rack North)	Overhead hazardous waste E	Light Liquid	Hazardous Waste	IA		0	0	0 1	٥ ،	0	0 0	0	IN
9973.01	Valve - Ball	Valve	2	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead hazardous waste line to plate W	Light Liquid	Hazardous Waste	IA		1	0	0 2	1 1	0	0 0	0	IN
9973.02	Flange	Fitting	2	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead hazardous waste line to plate W	Light Liquid	Hazardous Waste	IA		0	0	0 1	٥ ،	0	0 (0	IN
9973.03	Valve - Ball	Valve	2	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead hazardous waste line to plate W	Light Liquid	Hazardous Waste	IA		1	0	0 2	2 1	0	0 (0	IN
9973.04	Valve - Ball	Valve	2	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead hazardous waste line to plate W	Light Liquid	Hazardous Waste	IA		1	0	0 2	1 1	0	0 (0	IN
9973.05	Hose Connection	Other	2	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead hazardous waste line to plate W	Light Liquid	Hazardous Waste	IA		0	0	0 0) 1	0	0 (0	IN
9973.06	Valve - Ball	Valve	2	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead hazardous waste line to plate W	Light Liquid	Hazardous Waste	IA		1	0	2 C	0	0	0 (0	IN
9973.07	Camlock Fitting	Other	2	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead hazardous waste line to plate W	Light Liquid	Hazardous Waste	IA		0	0	1 0) 1	0	0 (0	IN
9974.01	Flange	Fitting	2	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead vapor line to CVS W	Gas	Hazardous Waste	IA		0	0	0 1	. 0	0	0 0	0	IN
9974.02	Flange	Fitting	0.75	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead vapor line to CVS W	Gas	Hazardous Waste	IA		0	0	0 1	. 1	0	0 0	0	IN
9974.03	Threadolet	Fitting	0.25	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead vapor line to CVS W	Gas	Hazardous Waste	IA		0	0	1 0) 0	0	0 0	0	IN
9974.04	Tube Fitting	Fitting	0.25	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead vapor line to CVS W	Gas	Hazardous Waste	IA		0	0	1 C	0	0	0 0	0	IN
9974.05	Tee	Fitting	0.25	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead vapor line to CVS W	Gas	Hazardous Waste	IA		0	0	3 C	0 0	0	0 0	0	IN
9974.06	Tube Fitting	Fitting	0.25	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead vapor line to CVS W	Gas	Hazardous Waste	IA		0	0	1 0	0	0	0 0	0	IN
9974.07	Sight Glass	Other	0.25	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead vapor line to CVS W	Gas	Hazardous Waste	IA		0	0	1 0) 1	0	0 (0	IN
9974.08	Valve - Control	Valve	0.5	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead vapor line to CVS (00 - 507) W	Gas	Hazardous Waste	IA		1	0	0 2	2	0	0 (0	IN
9975.00	Valve - Ball	Valve	0.5	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead vapor line to CVS W	Gas	Hazardous Waste	IA		1	0	2 C) 0	0	0 (0	IN
9975.01	4 Way	Fitting	0.5	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead vapor line to CVS center W	Gas	Hazardous Waste	IA		0	0	3 C	0	0	0 0	0	IN
9975.02	Gauge	Other	0.5	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead vapor line to CVS W	Gas	Hazardous Waste	IA		0	0	1 0) 1	0	0 0	0	IN
9975.03	Tube Fitting	Fitting	0.375	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead vapor line to CVS W	Gas	Hazardous Waste	IA		0	0	1 C) 0	0	0 (0	IN
9975.04	Union	Fitting	0.375	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead vapor line to CVS NW	Gas	Hazardous Waste	IA		0	0	2 C	0	0	0 (0	IN
9975.05	Valve - Ball	Valve	0.5	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead vapor line to CVS W	Gas	Hazardous Waste	IA		1	0	1 C	0	0	0 (0	IN
9975.06	Plug	Fitting	0.5	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead vapor line to CVS W	Gas	Hazardous Waste	IA		0	0	1 C	0	0	0 (0	IN
9975.07	Valve - Ball	Valve	2	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead vapor line to CVS W	Gas	Hazardous Waste	IA		1	0	0 2	2 1	0	0 (0	IN
9975.08	Hose Connection	Other	2	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead vapor line to CVS W	Gas	Hazardous Waste	IA		0	0	0 0) 1	0	0 (0	IN
9975.09	Valve - Ball	Valve	2	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead vapor line to CVS W	Gas	Hazardous Waste	IA		1	0	2 C) 0	0	0 0	0	IN
9975.10	Camlock Fitting	Other	2	DTO & Styrene Truck Loading	PR - 11 (Hazardous Waste Truck Rack)	Overhead vapor line to CVS W	Gas	Hazardous Waste	IA		0	0	1 C) 1	0	0 (0	IN
10230.00	Flange	Fitting	2	Hazardous Waste	T - 307 (Spent Tars Tank)	Top inlet E	Light Liquid	Hazardous Waste	IA		0	0	0 1	. 0	0	0 (0	IN
10230.01	Flange	Fitting	1.5	Hazardous Waste	T - 307 (Spent Tars Tank)	Top E	Light Liquid	Hazardous Waste	IA		0	0	0 1	. 0	0	0 (0	IN
10230.02	90 Degree	Fitting	1	Hazardous Waste	T - 307 (Spent Tars Tank)	Above E	Light Liquid	Hazardous Waste	IA		0	0	2 C	0 0	0	0 (0	IN
10230.03	Valve - Ball	Valve	1	Hazardous Waste	T - 307 (Spent Tars Tank)	Above E	Light Liquid	Hazardous Waste	IA		1	0	1 C) 1	0	0 (0	IN
10230.04	Plug	Fitting	1	Hazardous Waste	T - 307 (Spent Tars Tank)	Above E	Light Liquid	Hazardous Waste	IA		0	0	1 C	0 (0	0 (0	IN